Standard Operating Procedure of Optomec Aerosol Jet Printer in Pneumatic Atomizer Mode and Characterization of Printed PEDOT:PSS Lines



Kye Young Lee, Camila Cendra, Theo Gao

### Outline

#### 1. Introduction: drop-on-demand printing techniques

- 1. Working principles of aerosol jet printing
- 2. Examples/applications of aerosol jet printing
- 3. Comparison: aerosol jet vs. inkjet

### 2. Standard operating procedure (SOP) of Optomec

- 1. Assembly and initialization
- 2. Troubleshooting
- 3. Disassembly and cleaning

### 3. Aerosol jet printing - start atomizing!

- 1. Optimizing print patterns
- 2. Printing example: lines of PEDOT:PSS

### 4. Conclusion

### **1. Introduction: Drop-on-Demand Printing Techniques**



### 1.1 Working principles of aerosol jet printing



### 1.2 Examples/applications of aerosol jet printing



ACS Appl. Mater. Interfaces 2013, 5, 4856–4864 Adv. Electron. Mater. 2017, 3, 1700057



**Optomec Inc.** 



Damle et al., unpublished work

Flexible silver patterns

All-printed CNT transistor arrays

40

Conformal printing

CeO<sub>2</sub> micropillars

### 1.3 Comparison: aerosol jet vs. ink jet printing

#### Aerosol jet

- Compatible with a wide range of ink rheologies (1-5000 cP)
- Can pattern large areas, as well as on uneven surfaces
- Utilizes more material
- Less prone to clogging
- Suitable for single-material deposition

#### Inkjet

- Limited to low viscosity inks (<5 cP)</li>
- Limited to small areas and flat surfaces
- Less wasteful of material
- Prone to clogging
- Easier to do multimaterial printing



**Dimatix Printer 2800 Series** 





### 2. Standard Operating Procedure of Optomec in Pneumatic Mode

### 2.1 Assembly and initialization



#### Virtual impactor assembly

#### Pneumatic atomizer stem assembly



#### Printhead assembly for fine feature nozzle





Atomization of PEDOT:PSS ink when atomizer flow is on

A tube connects the virtual impactor with the printhead







Adjusting deposition head (nozzle tip) and shutter height using glass slides





### **2.2 Troubleshooting**

1. Software issues -- not starting or freezing, not executing the uploaded toolpath file, not measuring applied gas flow values

→ Close/restart KEWA, restart computer, set all gas flows to zero in proper order
2. Unusual gas flow values (leakage or clogging)

- → Check for leaks in tubing, printhead, virtual impactor & atomizer (in that order)
- $\rightarrow$  Clean or replace parts as needed
- 3. Bad jetting behavior
  - $\rightarrow$  Adjust "push" ( $\Delta$  of exhaust & atomizer flow)
  - $\rightarrow$  Adjust height of atomizer in the jar
  - $\rightarrow$  Dilute ink to reduce viscosity





### **2.2 Troubleshooting**

1. Software issues -- not starting or freezing, not executing the uploaded toolpath file, not measuring applied gas flow values

→ Close/restart KEWA, restart computer, set all gas flows to zero in proper order 2. Unusual gas flow values (leakage or clogging)

- $\rightarrow$  Check for leaks in tubing, printhead, virtual impactor & atomizer (in that order)
- $\rightarrow$  Clean or replace parts as needed
- 3. Bad jetting behavior
  - $\rightarrow$  Adjust "push" ( $\Delta$  of exhaust & atomizer flow)
  - $\rightarrow$  Adjust height of atomizer in the jar
  - $\rightarrow$  Dilute ink to reduce viscosity





### 2.3 Disassembly and cleaning

#### After printing, the Optomec must be promptly disassembled and cleaned

- 1. Turn off the three gas flows in the following order: **atomizer**  $\rightarrow$  **wait** 10s  $\rightarrow$  **exhaust**  $\rightarrow$  **wait** 60s  $\rightarrow$  **sheath**
- 1. Remove pneumatic atomizer, virtual impactor, printhead  $\rightarrow$  disassemble
- 2. Disassemble the printhead-shutter subassembly
- 3. Dispose of tubing
- 4. Clean up the work stage

#### **Cleaning procedure**

<b>Cleaning solution</b>	Non-critical parts	<b>Critical parts</b>	Critical parts (no Branson)
1) Water	$10\min \times 2$ times	$10\min \times 2$ times	20min × 3 times
			(or $10\min \times 5 \text{ times})^*$
2) Branson	$10\min \times 2$ times	$10\min \times 3$ times	
3) Isopropyl alcohol	$10\min \times 2$ times	$10\min \times 3$ times	$10 \min \times 3 $ times
() Dinge with isomeonyl clock of and blow day with N gun			

4) Rinse with isopropyl alcohol and blow dry with N<sub>2</sub> gun

Thorough cleaning is the most critical step in Optomec SOP!





### 3. Aerosol Jet Printing: Start Atomizing!







### 3.1 Optimizing print patterns



### 3.1 Optimizing print patterns



### **3.2 Printing PEDOT:PSS**









#### 4-point probe conductivity: 14.12 ± 10 S/cm

#### In literature: 14.82 S/cm

## 4. Conclusion

### 4. Conclusion

#### Summary

Drop-on-demand printing techniques: aerosol jet vs. ink jet

Standard operating procedure of Optomec in pneumatic mode

Optimizing print patterns and characterization of PEDOT:PSS lines

#### **Suggestions for future users**

Expand allowed solvents for Optomec to include common organic solvents

> Purchase a new atomizer lid-jar

Develop leak detecting protocol to streamline the troubleshooting process

#### Thank you:

Hye Ryoung Lee, Swaroop Kommera, Randall Stoltenberg, Antonio Ricco, Donald Gardner

# **Any Questions?**

